

Kingston (CP) - Locations by Mileage

0	Renfrew	
0	McLachlan branch	Auth. by 39766.
0.22	Munroe Street	Verified from 85469.
0.28	Raglan Street	Also Chalk River sub.
0.36	Argyle Street	Also Chalk River sub.
1.08	Canadian Oil Companies	Verified from 107131.
1.12	Imperial Oil	Verified from 107751 - Renfrew sub.
1.3	Renfrew Junction	
2.1	Crossing	
2.83	Douglas Road	Verified from 98826.
3.2	Crossing	
4.05	Crossing	
4.51	Opeongo	
5.25	Crossing	
6.75	Crossing	
7.7	Crossing	
8.36	Development Road 541.4	Verified from 124237.
9.4	Peros Lake	
10	Crossing	Verified from 58224, lots 27 & 28, conc. 8, Bagot & Blythfield.
10.19	Crossing	Verified from 58224, concs. 8 & 9, Bagot & Blythfield.
10.51	Ashdod	
10.54	Crossing	Verified from 58224, lw. half lot 26, conc. 8, Bagot & Blythfield.
11.42	Crossing	Verified from 58224, lots 24 & 25, conc. 9, Bagot & Blythfield.
12.05	Norway Lake	
12.59	Crossing	Verified from 58224, lots 24 & 25, conc. 9, Bagot & Blythfield.
13.9	Crossing	
14.1	Wye	14.1 to 14.2 one mile spur north to Lake Calabogie.
14.15	Crossing	
14.26	Madawaska River, North	100' Deck truss. earlier D. Lattice Girder span, masonry abutments; originally through Howe truss 150 ft. span
14.28	Bridge	100' half DPG
14.29	Crossing	Verified from 58224, east half lot 18, conc. 10, Bagot & Blythfield.
14.41	Calabogie	Station west side, freight shed east side.
14.43	Madawaska River, South	100' 8" T. P. Girder span, masonry abutments.
14.44	Crossing	
15	Crossing	
15.08	O'Brien siding	Auth. by 26212.
15.34	Culvert	17' wooden wall, Grassy Bay. Later 25' 11" pile bridge.
15.7	Culvert	17' wooden wall, Grassy Bay. Later 21' 6" pile bridge.
15.8	Siding	740' North side.
16	Crossing	Verified from 58224, lots 15 & 16, conc. 12, Bagot & Blythfield.
16.21	Barryvale	Station east side.
16.9	Crossing	
17.7	Crossing	
18.35	Crossing	Verified from 58224, west half of lot 11, conc. 1, Bagot & Blythfield.
19	Crossing	
20.2	Crossing	
21.25	Crossing	
22.6	Crossing	
22.75	Crossing	
23.6	Clyde River	
24.1	Clyde River	
24.4	Crossing	
24.5	Culvert	10' rail concrete.
25.35	Crossing	
25.39	Flower	
25.45	Crossing	Verified from 58008.

26.2	Crossing	
26.85	Crossing	
27.01	Bridge	4 I beams 23' long. Later 24'9" pile bridge.
27.33	Clyde Forks	Clyde Forks spur.
27.4	Culvert	10' wooden wall. Later 24'9" pile bridge.
27.48	Bridge	15' 0" pile bridge.
27.5	Bridge	15' 7" pile trestle
27.75	Crossing	Verified from 58008.
28	Crossing	Verified from 58008.
29	Crossing	
29.72	Crossing	Verified from 58008.
30.18	Clyde River	42' 10" D Pl girder span, masonry abutments; originally Deck Howe truss 60 ft.
30.5	Crossing	Verified from 58008.
31.51	Crossing	Verified from 58008.
31.6	Crossing	
31.76	Culvert	11' wooden wall.
32.12	Folger	Station west side, 929' double ended siding west side, 808' single ended siding east side, switch south end.
32.44	Culvert	19' wooden wall.
32.69	Culvert	10' R C G
33.06	Crossing	Verified from 58008.
33.52	Culvert	10' wooden wall. Later 10' 7" pile trestle.
34.28	Crossing	Verified from 58008.
34.29	Lavant	Station west side, 894' siding west side double ended.
35.35	Crossing	County and twp. boundary, verified from 58008.
35.37	Crossing	Verified from 58008.
36.2	Wilbur	
36.9	Wilbur Mines Junction	Junction with Wilbur Mines branch.
37.37	Crossing	Verified from 58008.
37.6	Crossing	
38.6	Crossing	Verified from 58008.
38.7	Culvert	10' wooden wall.
39.63	St. Antoinies Creek	Culvert, 14' rail concrete.
39.96	St. Antoinies Creek	Culvert, 14' rail concrete.
40.25	Crossing	Verified from 58008.
40.3	Crossing	
40.55	St. Antoinies Creek	17' 6" D Pl girder span, concrete abutments.
40.9	Crossing	Verified from 58008.
41.76	St. Antoinies Creek	17' 6" D Pl girder span, concrete abutments.
42.25	Snow Road	Station east side, 896' double ended siding, west side.
42.26	Crossing	Verified from 58008.
42.51	Crossing	Verified from 58008.
42.7	Crossing	
42.75	Chandler Jones spur	West side.
42.8	Mississippi River	Bridge No. 42.8, 56' D Pl girder span, trestle approaches. Originally Howe truss 78 ft. span.
43.1	Crossing	
43.9	Crossing	
44.15	Crossing	Verified from 58008.
44.17	Mississippi	Station west side, 1226' double ended siding east side.
44.27	Black Creek	Culvert. 20' wooden wall.
44.3	Crossing	
44.35	Siding	East side, single ended, switch south end.
44.35	Crossing	Verified from 58008.
44.66	Black Creek	Culvert, 23' wooden wall.
44.86	Black Creek	23' D Pl girder span, concrete abutments.
44.9	Crossing	
45.53	Black Creek	Culvert, 14' rail concrete.
45.6	Crossing	
46.25	Crossing	Verified from 58008.
46.4	Spur	1 mile long north east.
46.43	Robertsville	

46.44	Black Creek	4 I beams, 27' long.
47.26	Crossing	Twp. boundary, verified from 58008.
47.76	Crossing	Verified from 57975.
48	Crossing	Verified from 57975.
48.02	Clarendon	Station west side, double ended siding west side, 1280'.
48.1	Crossing	
49.6	Crossing	
50.27	Bolton Creek	4 I beams, 24' long.
50.63	Bolton Creek	4 I beams, 27' long.
50.76	Bolton Creek	Culvert, 21' wooden wall.
51.4	Crossing	
52.1	Crossing	
53.21	Crossing	Verified from 57975.
53.37	Oso	
53.38	Crossing	Verified from 57975.
54.9	Forced Road	Verified from 49527, in lot 17, conc. 2, Oso twp.
55.46	Culvert	10' wooden wall.
56.25	Spur	North east.
56.3	Crossing	
56.65	Sharbot Lake	Station in V with CPR, north end
56.7	Crossing	Verified from 57975, conc. 1, lot 13, Oso twp.
56.95	Crossing	Verified from 57975.
57.17	Bridge	4 I beams 26' long, masonry abutments.
57.28	Sharbot Lake Narrows	Verified from 83160.
57.7	Crossing	Verified from 57975.
58.45	Crossing	Twp. boundary.
59.7	Crossing	Twp. boundary.
59.75	Culvert	13' wooden wall.
60.8	Crossing	Verified from 57975.
61.44	Oconto	
61.75	Crossing	Twp. boundary, Oso/Olden.
61.95	Crossing	Twp. boundary, Bedford/Olden.
62.5	Crossing	
62.7	Crossing	
63.5	Crossing	
64.34	Crossing	Twp. boundary, Bedford/Hinchinbrooke
64.9	Crossing with CLO&W	
65.14	Tichborne Junction	Originally Parham, station east side, 1032' double ended siding west side.
65.23	Crossing	Verified from 57975.
66.25	Crossing	
66.45	Elbow Creek	4 I beams, 17' 6" long, masonry abutments; originally two queen post trusses 17 ft. span each.
66.63	Crossing	Verified from 57975.
67.2	Crossing	Verified from 57975.
68.95	Crossing	
69.25	Crossing	
69.62	Crossing	Verified from 57975.
70.8	Culvert	12' R C C.
71.22	Highway 38	Verified from 116702.
71.23	Hinchinbrooke	
71.35	Crossing	Verified from 57975.
73.36	Crossing	Verified from 113832.
73.55	Highway 38	Verified from 116644.
73.71	Crossing	Verified from 57975.
73.8	Bridge	4 I beams, 18' 11' long, masonry abutments.
74.02	Godfrey	Junction with Glendower Mines Branch or Bedford Branch
74.04	Westport Road	Verified from 118856.
74.17	Crossing	Verified from 57975.
74.44	Crossing	Verified from 57975.
74.77	Crossing	
74.92	Crossing	Verified from 57975.

75.25	Crossing	Twp. boundary Hinchinbrooke/Portland.
76.35	Crossing	Verified from 57113, conc. 13, lot 8, Portland twp.
77.27	Highway 38	Verified from 107087, 57113 shows 77.26, conc. 12, lot 8, Portland twp..
77.3	Culvert	11' wooden wall.
77.9	Crossing	Verified from 57113, concs. 11 7 12, Portland twp.
78.48	Verona	Station east side, 1139' dbl ended siding west side, 595' sgl ended siding west side switch n. end.
78.5	Crossing	
78.62	Bank Street	Verified from R-18657, village of Verona.
78.76	Bellrock Road	Verified from 57113, village of Verona.
79.07	Depot Street	Verified from 57113, village of Verona.
79.15	Napanee River	42' 10" H D Pl girder span, masonry abutments; originally queen post truss 32 ft. span.
79.6	Crossing	
80.1	Kingstons crossing	Verified from 28135.
80.8	Crossing	
81.91	Hartington	21.5 from Kingston.
82.1	Crossing	
82.8	Crossing	
83.7	Crossing	
84.75	George Street	Verified from 103535. 57113 shows 84.73, between concs. 4 & 5, Portland twp.
84.82	County Road 4A	Verified from R-10583.
84.83	Harrowsmith	Junction with CNOR, station east side,
84.98	Highway 38	Verified from 96722, also Kingston Street..
85.22	Wilton Street	Verified from 44593.
86.73	Crossing	Verified from 57113, concs. 3 & 4, Portland twp.
87.2	Mud Creek	42' 10" H D Pl girder span, masonry abutments, originally Queen post truss 32 ft.
87.6	Crossing	
88.8	Crossing	
89.2	Crossing	
89.32	Murvale	Station west side, 923' dbl ended siding east side.
89.9	Crossing	Twp. boundary, Portland/Kingston.
91.7	Crossing	
93.17	Glenvale Road	Verified from 123834.
93.22	Glenvale	Station east side, dbl ended siding 1083' west side.
94.6	Crossing	
95.95	Crossing	
96.9	Crossing	
97.08	Highway 401	Verified from 86779.
97.45	Crossing	
97.64	Knight's siding	
98.33	Sydenham Crossing	Verified from 96571.
98.51	Texaco Canada	Verified by 108579.
99.05	Bridge	4 I beams 21' 4" long, masonry abutments.
100.26	Dalton Street	Verified from R-4478.
100.91	Division Street	Verified from 123671.Originally Perth Road also Glenburnie Road.
101.34	Norman Spur	Verified from 65663.
101.47	Reliance Moulding spur	Verified from 22704, east side, 1374'.
101.5	Elliott Street	Verified from 48312.
101.58	Frontenac Floor and Wall Tile	Auth. by 20775.
101.7	Crossing with GTR	
101.91	Nicholson siding	Auth. by 84135.
101.98	Quintane gas	Verified from 98070.
101.98	I. Cohen Siding	Verified from R3891.
102	Hickson Avenue	
102.02	MacCosham Van Lines Siding	Verified from R-3631.
102.1	Montreal Street	Verified from 90749. Crossing with KP&C Electric Street Rly.
102.2	Watson Lytton spur	Auth. by 32803.
102.2	River Street	
102.25	Cataraqui Street	
102.5	Crossing with CNR	Verified from 88649, this is siding trackage.
102.6	Cataraqui Street	Verified from 48312.

102.6	Dominion Textiles branch	Auth. by 37881.
102.6	Kingston crossing	Crossing with GTR
102.7	Kingston Smelting	Auth. by 26259.
102.75	Day Street	Verified from 48312.
102.9	Round House	
103	Ontario Street	
103.08	Place D'Armes Street	Verified from 29727.
103.2	Place d'Armes Street	Verified from 90211.
103.21	Anglin Co Siding	Verified from R-3267.
103.25	James Sowards Coal Spur	Verified from 65657.
103.4	Brock Street	
103.43	Kingston	