

NYC Maintenance of Way 18 January 1956

From	To	Length	Weight	Brand	New	Condition
Helena						
62.79	66.08	3.29	80	LSCO OH	-	C
Rooseveltown						
66.08	67.25	1.17	80	LSCO OH	1908	B
International Boundary						
67.25	68.1	0.85	80	Cammal	1895	B
Uscan						
68.1	69.29	1.19	80	Cammal	1895	B
Cornwall						
69.29	70	0.71	80	Cammal	1895	B
70	70.13	0.13	80	Cammal	1896	B
Cornwall jct						
70.13	70.14	0.01	80	Cammal	1895	B
70.14	70.16	0.02	100	CAI RA A20 L15	1907	B
70.16	75.13	4.97	80	Cammal	1896	B
75.13	77.29	2.16	80	Cammal	1896	B
Black River						
77.29	78.89	1.6	80	Cammal	1896	B
Harrison						
78.89	79.97	1.08	80	Cammal	1896	B
79.97	81.08	1.11	80	LSCO OH	1908	B
81.08	81.72	0.64	80	Cammal	1896	B
Northfield						
81.72	83.03	1.31	80	Cammal	1896	B
83.03	84.13	1.1	80	Moss Bay	1896	B
84.13	84.78	0.65	80	Cammal	1896	B
Newington						
84.78	87.08	2.3	80	Cammal	1896	C
87.08	87.29	0.21	80	Moss Bay	1901	C
87.29	87.78	0.49	80	LSCO OH	1918	B
87.78	88.81	1.03	80	Moss Bay	1901	C
88.81	88.9	0.09	80	Cammal	1896	B
88.9	88.91	0.01	105	BSCO	1926	B
Finch						
88.91	88.93	0.02	105	BSCO	1926	B
88.93	89.01	0.08	80	Cammal	1896	B
89.01	89.79	0.78	80	Moss Bay	1901	B
89.79	90.36	0.57	80	LSCO OH	1918	B
90.36	91.28	0.92	80	Moss Bay	1901	B
Berwick						
91.28	93.19	1.91	80	Cammal	1896	B
93.19	94.59	1.4	80	Johnson Lorraine	1900	B
Crysler						
94.59	95.1	0.51	80	Johnson Lorraine	1900	B
95.1	97.16	2.06	80	LSCO OH	1910	B
St. Albert						
97.16	98.57	1.41	80	LSCO OH	1910	B
Cambridge						
98.57	100	1.43	80	LSCO OH	1910	B
100	101.13	1.13	80	West rail LSCO OH	1911	B

A - very good - no perceptible wear.
 B - slightly worn but good.
 C - much worn.

NYC Maintenance of Way 18 January 1956

101.13	101.63	0.5	80	West rail LSCO OH	1912	B
101.63	102.12	0.49	80	West rail LSCO OH	1911	B
102.12	102.16	0.04	80	West rail LSCO OH	1910	B
100	101	1	80	East rail LSCO OH	1911	B
101	101.6	0.6	80	East rail LSCO OH	1911	B
101.6	102.12	0.52	80	East rail LSCO OH	1911	B
102.12	102.16	0.04	80	East rail LSCO OH	1910	B
102.16	102.24	0.08	80	LSCO OH	1911	B
102.24	102.33	0.09	80	LSCO FT	1910	B
Embrun						
102.33	102.58	0.25	80	West rail LSCO OH	1913	B
102.58	102.65	0.07	80	West rail LSCO OH	1910	B
102.65	102.76	0.11	80	West rail LSCO OH	1913	B
102.76	104.27	1.51	80	West rail LSCO OH	1911	B
104.27	105.56	1.29	80	West rail LSCO OH	1913	B
105.56	105.76	0.2	80	West rail LSCO OH	1912	B
105.76	105.93	0.17	80	West rail LSCO OH	1913	B
102.33	102.37	0.04	80	East rail LSCO OH	1920	B
102.37	102.76	0.39	80	East rail LSCO OH	1913	B
102.76	103.6	0.84	80	East rail LSCO OH	1911	B
103.6	105.65	2.05	80	East rail LSCO OH	1913	B
105.65	105.88	0.23	80	East rail LSCO OH	1912	B
105.88	105.93	0.05	80	East rail LSCO OH	1913	B
Russell						
105.93	107.92	1.99	80	West rail LSCO OH	1913	B
105.93	106.12	0.19	80	East rail LSCO OH	1913	B
106.12	106.16	0.04	80	East rail LSCO OH	1917	B
106.16	107.92	1.76	80	East rail LSCO OH	1913	B
107.92	109.25	1.33	80	LSCO OH	1916	B
Pana						
109.25	109.3	0.05	80	LSCO OH	1916	B
109.3	109.35	0.05	80	LSCO OH	1910	B
109.35	110	0.65	80	LSCO OH	1916	B
110	112.48	2.48	80	LSCO OH	1917	B
112.48	112.67	0.19	80	LSCO	1910	B
Edwards						
112.67	112.76	0.09	80	LSCO	1910	B
112.76	115.49	2.73	80	LSCO OH	1917	B
Piperville						
115.49	116.11	0.62	80	LSCO	1917	B
116.11	118.89	2.78	80	LSCO	1917	B
Ramsayville						
118.89	120.41	1.52	80	LSCO	1917	B
120.41	120.51	0.1	80	Moss Bay	1895	B
120.51	120.53	0.02	100	Can Algoma A	1920	B
120.53	120.57	0.04	80	Moss Bay	1895	B
Hawthorne						
120.57	120.63	0.06	80	Moss Bay	1895	B
120.63	121.94	1.31	80	LSCO	1917	B
121.94	124.1	2.16	80	Moss Bay	1896	B
Hurdman						

A - very good - no perceptible wear.

B - slightly worn but good.

C - much worn.

NYC Maintenance of Way 18 January 1956

Hurdman Junction

124.78	124.97	0.19	80	Cammal	1901	B
124.97	125.23	0.26	80	LSCO/Cammal	1916/1901	B

Ottawa

Total 60.89

Note Finch crossing frogs installed 1929.

- A - very good - no perceptible wear.
- B - slightly worn but good.
- C - much worn.